## Controlled Dryer Shutdown

- 1. On the DDGS page:
  - a. Click on YV-52206 (Wetcake slide gate)
    - i. Take setting to 100
    - ii. Click OK
- 2. The wetcake is now being diverted to the wetcake pad.
- 3. Click on Green Button labeled HTGR-11
  - a. Put in Manual
    - i. Click OFF
  - b. Turn off X-5206 Recycle Conveyor
  - c. Turn off X-5208 Mixer
  - d. Turn off X-5209 Drum inlet Conveyor
  - e. Turn off X-5230 Drum inlet conveyor
- 4. Let the Drum empty out into Fluid Bed for 20 minutes
  - a. Turn off RV-5218 Rotary Valve into fluid bed
- 5. Let all other equipment run to empty out the drum
- 6. Leave RTO run